



Casio HT-3000/700 Modification

Cut trace and new cable for cutoff



Desoldered
pin and new
cable for
resonance

Replaced
resistor
5,1 k -> 10k



47 k lin pot and
75 k Resistor

22 k lin pot and
two 22 k Resistors